

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle

Basketball Courts

Overall Evaluation – Average Condition

- Surfaces had some cracks but did not represent a safety hazard.
- One of six hoops had torn nets.
- One of six hoops was bent.



This basketball court had a smooth, even surface. Both courts had hoops with backboards and nets in good condition. The court lines were clearly painted.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle



This hoop had a torn net and some rust on the backboard and pole.



This hoop was bent.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle

Baseball Fields

Overall Condition – Poor Condition

- Playing surfaces were hard and uneven.
- Playing surfaces needed new athletic mill (baseball infield surface material).
- Backstops had broken fences and broken boards.
- Low fences at the bench area did not provide adequate protection for players.
- Weeds were growing on the infield.
- Large divots in the infield were a safety hazard.



This backstop had a broken fence and broken boards.